


HIPERDRIVE POSITIONING SYSTEMS

The HIPERDRIVE series facilitates both direct wiring and indirect wiring via a Hub (see p. 8 + 9).



A direct wiring (adapter) → see p. 40

B indirect wiring via Hub → see p. 41

ACCESSORIES FOR HIPERDRIVE HDA 70 AND PSE 441

HDA 70 with bus communication (Industrial Ethernet ¹⁾ and PROFIBUS DP)				
A	Bus cable for Industrial Ethernet with an M12 connector (D-cod.) 10 m: Order no. 9508.0045 20 m: Order no. 9508.0046		Power supply cable with a 7/8" connector socket 10 m: Order no. 9508.0043 20 m: Order no. 9508.0044	
	Bus cable for PROFIBUS DP with an M12 connector socket (B-cod.) 10 m: Order no. 9508.0011 25 m: Order no. 9508.0017		Connector for PROFIBUS DP M12 connector socket (B-cod.) Order no. 9508.0027	
	Connector set for PROFIBUS DP: 7/8" power supply connector + databus connector and socket Order no. 9508.0034		Connector for PROFIBUS DP M12 connector (B-cod.) Order no. 9508.0012 with terminating resistors: Order no. 9508.0013	
HDA 70 with RS485 (for indirect cabling via Hub)				
B	Simple flange adapter with cable: 1 m: Order no. 9508.0038 2 m: Order no. 9508.0033 5 m: Order no. 9508.0019 10 m: Order no. 9508.0010 15 m: Order no. 9508.0008		Connecting cable (with crimp contacts at one end) without adapter 2.5 m: Order no. 9508.0030	
			Adapter without cable Order no. 9508.0009	
PSE 441 with RS 485				
	Power supply and bus cable with an M12 connector socket (A-cod.) 10 m: Order no. 9508.0022 15 m: Order no. 9508.0035		Connector M12 connector socket (A-cod.) for PSE441 master Order no. 9601.0144	
			Connector M12 connector (A-cod.) for PSE441 slave drive Order no. 9601.0152	

¹⁾ EtherCAT, PROFINET, EtherNet/IP